

WFD-27 Wi-Fi Command Station/Booster

Known Issues, Workarounds and Fix Dates

This document is online at <http://www.wifitrax.com/manuals/WFD-26-27-28/WFD-27-known-issues.pdf>.

Please see our website for information on our limited warranty.

WifiTrax Model Science



www.wifitrax.com

© WifiTrax Model Science 2026 All Rights Reserved

Known Firmware/Hardware Issues

Description	F/W Version found	Work Around	F/W Version Fixed	Comments Relating to fix
A slight buzzing noise is emitted from the WFD-27 module	All	<p>This is coming from the large half-bridge driver modules that supply the DCC to the track. It is internal to the design of those modules.</p> <p>If you find it annoying mount the WFD-27 in a suitable plastic box. Remember to allow enough room for air flow in the box and provide some ventilation</p>		Not a fixable problem. We may change the drivers at some point.
Digitrax DS52 Point decoder does not work with the WFD-27		<p>This has been reported by a customer. There is no known workaround.</p> <p>It has not yet been evaluated</p>		<p>This may be due to the way Digitrax expects DCC commands to be formatted and be solvable by a firmware change.</p> <p>DCC Concepts ADS-2sx and 4sx work perfectly well, and of course Wifitrax WFS-47/87.</p>

--	--	--	--	--